

TK3 Firmware Release Notes

Release Date: 2025.02.25

TK3 Firmware Version: TK3_V01.01.02.00

Supported Products and Firmware Version:

Czi Sound: V1.1.3

Czi Assistant: V1.0.66

M30 series + DJI RC Plus

Aircraft firmware: V10.01.05.04

Remote control firmware: V05.02.13.02

Battery firmware: V02.00.20.58

M300 RTK + DJI RC Plus

Aircraft firmware: VV10.01.08.01

Remote control firmware: V10.01.08.01

Battery firmware: V01.02.05.44

M350 RTK + DJI RC Plus

Aircraft firmware: VV10.01.08.05


Remote control firmware: V05.02.13.02

Battery firmware: V09.03.00.48

What has been updated?

1. Optimize the firmware update speed and log export speed.
2. Optimize some known problems.

<http://www.gzczzn.com/>



Copyright © 2025 CZI All Rights Reserved

TK3 Firmware Release Notes

Release Date: 2024.08.01
TK3 Firmware Version: TK3_V01.00.06.00

Supported Products and Firmware Version:

Czi Sound: V1.1.3

Czi Assistant: V1.0.35

M30 series + DJI RC Plus

Aircraft firmware: V10.00.06.08

Remote control firmware: V05.02.11.06

Battery firmware: V02.00.20.58

M350 RTK + DJI RC Plus


Aircraft firmware: VV10.00.06.02

Remote control firmware: V05.02.10.00

Battery firmware: V09.03.00.47

What has been updated?

1. Added support for M350 aircraft.
2. Added user manual switching of transmission frequency function.
3. Fixed the issue of inconsistent battery status after multiple insertions and removals.
4. Fixed the inaccurate reading of sky-end voltage.
5. Optimized the upgrade process for intelligent voice firmware.
6. Removed the ladder voltage adjustment feature.
7. Adjusted the calculation formula for high-voltage voltage.
8. Removed the function of adjusting voltage when turning off the light.



9. Fixed the issue of reporting sky-end failure when the ground power is turned off.
10. Distinguished between lamp failures and low lamp power.